

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,940,321 B2
APPLICATION NO. : 10/728630
DATED : September 6, 2005
INVENTOR(S) : Heo et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

At cover sheet, item 56, foreign patent documents, please replace "KR 2003"
with --KR 2000--

At column 8, line 1, please replace "sign" with --signal--

At column 8, line 9, please replace "to last pulse" with --to a last pulse--

At column 8, line 19, please replace "lock" with --clock--

At column 8, line 37, please replace "clack" with --clock--

At column 8, line 45, please replace "a preamble control signal" with --the
preamble and the third output signal--


At column 8, line 62, please replace "A circuit, comprising" with --A circuit
comprising--

At column 9, line 7, please replace "first an second" with --first and second--

At column 10, line 11, please replace "A circuit, comprising" with --A circuit
comprising--

Signed and Sealed this

Twelfth Day of December, 2006



JON W. DUDAS
Director of the United States Patent and Trademark Office